

Garden Grove Hyundai 9898 Trask Avenue Garden Grove, CA 92844 (714) 741-3100 HYUNDRI www.gghyundai.com R/O Open Date 8/14/14 R/O Close Date 6090621/1 SERVICE DEPARTMENT HOURS Status 7:30 a.m. to 6:00 p.m. Monday - Friday 8:00 a.m. - 4:00 p.m.-Saturday Pre-Invoice MaageOut 8/14/14 Mileage In 22989 22989 Service Advisor / Tog # ROBERT MCCOOL/211 Vehicle Identification Number ARD00255045 Work Phone SAITTA, LUCIA 5XYZK4AG3CG118384 Home Phone Delivery Date In-Service Date Body License Number FWD V6 LTD NAV MO 2012 HYUNDAI SANTA FE V6 L

#1 - Customer Reports: CUSTOMER STATES PERFORM SERVICE CAMPAIGN 929 CHECK AND ADVISE Caused by TECH FOUND OPEN CAMPAIGN FOR IDEL IMPROVEMENT # 929 IDEL IMPROVMENT (TSB 14-01-028) Corrected by Work performed by ALEX RIOS (241) COMPLETED CAMPAIGN OK AFTER REPAIR #2 - Customer Reports: CUSTOMER STATES THERE IS A WHINEING GROWLING FROM THE ENGINE ON LIGHT ACCELERATION, CHECK AND ADVISE Caused by TECHNICIAN TRACED NOISE COMING FROM ENGINE ILDER PULLY, EXCESSIVE PLAY CAUSING ABNORMAL NOISE Corrected by (N29) (C11) IDLER PULLEY RE Work performed by ALEX RIOS (241) Warrant	DESCRIPTION OF SERVICE AND PARTS Cell: 714-343-5779 Email: calzoneluci	a@vahoo.com	TRUOMA
CUSTOMER STATES THERE IS A WHINEING GROWLING FROM THE ENGINE ON LIGHT ACCELERATION, CHECK AND ADVISE Caused by TECHNICIAN TRACED NOISE COMING FROM ENGINE ILDER PULLY, EXCESSIVE PLAY CAUSING ABNORMAL NOISE COTTECTED BY (N29) (C11) IDLER PULLEY RE Work performed by ALEX RIOS (241) Installed 25286-3C250: PULLEY-IDLER Qty: 1 REMOVE AND REPLACED ILDER PULLY, OK AFTER REPAIR #3 - MPI: MULTI-POINT INSPECTION INSPECT LIGHTS, LENSESUNDER HOOD, CABIN & AIR FILITERS, FOR FLUIDLEAKS, BELTS, BR AKES, BATTERY, TIRE PRESSURES, TOP OFF UNDER HOOD FLUIDS, RF LF RR LR Work performed by ALEX RIOS (241) WORK performed by ALEX RIOS (241) MPI COMPLETE **AN Expression of the production of the policy of the for delays in parts of the policy in parts of delays in parts plated by the supplier or transporter. I harbey grant you or your employees permission to be done along with this necessary makeful and agree thely you are not responsively to parts or delays in parts plated by the supplier or transporter. I harbey grant you or your employees permission to resten the vehicle or attracted by unavestability of parts or delays in parts grants belowed your control of for any delays caused by unavestability of parts or delays in parts grants belowed your control of the parts of the parts of the state of the parts of the part	#1 - Customer Reports: CUSTOMER STATES PERFORM SERVICE C CHECK AND ADVISE Caused by TECH FOUND OPEN CAMPAIGN FOR ID # 929 IDEL IMPROVMENT (TSB 14-0 Corrected by Work performed by ALEX RIOS	AMPAIGN 929 DEL IMPROVEMENT (241)	Warranty
A highenoide to be done along with the necessary material and agree that you are not respons- for loss or damage to vehicle or articles left in the vehicle in case of fire, lineth, or any other size beyond your control or for any delays caused by unaveilability of parts or telegy in parts protects by the supplier or transporter. I hereby grant you or your employees permission to prate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing for inspection. An express mechanic's lian is hereby acknowledged on above vehicle to secure amount of regains thereto." SCLAIMER OF WARRANTIES. Any werrenties on the products sold hereby are those made by municipal warranty of mechanicality or harves for a particular purpose, and the abler notiner any implies warranty of mechanicality or harves for a particular purpose, and the abler notiner turned and warranty of mechanicality or harves for a particular purpose, and the abler notiner turned and the products and one secure for it any liability in connection with the sele of d products. Any timitation contained herein does not apply whose promibled by kny. PARTS DEDUCTIBLE SUBLET SHOP SUPPLIES HAZARDOUS MATERIALS SALES TAX OR TAX I.D. SPECIAL ORDER DEPOSIT DISCOUNTS DISCOUNTS	CUSTOMER STATES THERE IS A WHINEI THE ENGINE ON LIGHT ACCELERATION, Caused by TECHNICIAN TRACED NOISE COMING PULLY, EXCESSIVE PLAY CAUSING A Corrected by (N29) (C11) IDLER PU Work performed by ALEX RIOS Installed 25286-3C250 :PULLEY-IDL REMOVE AND REPLACED ILDER PULLY, #3 - MPI: MULTI-POINT INSPECTION INSPE HOOD, CABIN & AIR FILTERS, AKES, BATTERY, TIRE PRESSUR FLUIDS, RFLFRRL WORK PERFORMED BY ALEX RIOS	CHECK AND ADVISE FROM ENGINE ILDER ABNORMAL NOISE ULLEY RE (241) AER Qty: 1 OK AFTER REPAIR CCT LIGHTS, LENSESUNDER FOR FLUIDLEAKS, BELTS, BR AES, TOP OFF UNDER HOOD AR	Warranty Warranty
	In the penditor to be done along with the necessary material and agree that you are not respons- to for loss or damage to vehicle or articles left in the vehicle in case of fire, then, or any other tion beyond your control or for any delays caused by unaveilability of parts or delays in a parts ignitions by the supplier or transporter. I hareby grant you or your employees permission to erate the vehicle herein described on streets, highways, or elsewhere for the purpose of teeling dior inspection. An express mechanic's lian is hereby acknowledged on above vehicle to accure a amount of repairs thereto. SCLAMER DF WARRANTIES. Any werrenites on the products sold hereby are those made by a manufacturer. The soliter hereby expressly disclaims all watranties either express or implied, includ- gray implied warranty of merchantalisticy or bitness for a particular purpose, and the author nother	PARTS DEGUCTIBLE SUBLET SHOP SUPPLIES HAZARDOUS MATERIALS SALES TAX OR TAX I.D. SPECIAL ORDER DEPOSIT DISCOUNTS	